

RECEIVED
IN THE UNITED STATES PATENT AND TRADEMARK OFFICE **CENTRAL FAX CENTER**

Owner: SANDERS, Allan OCT 21 2005

Patent No: 6,883,300 (Serial No 10/617,179)

Issued: April 26, 2005 (Filed July 11, 2003)

Title: ASSEMBLY INCLUDING A CHAIN FOR SUSPENDING AN ARTICLE SUCH AS A LIGHT AND FOR CONCEALING AN ELECTRICAL CONDUCTOR

Art Unit: 3725 Certificate

Confirm: 3035 OCT 25 2005

Our File: RE-SANDE-03.US (5280-03-60) of Correction

October 21, 2005
By Fax 1-571-273-8300

Attention: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
U.S.A.

Dear Sir:

Certificate of Facsimile Transmission

I, the undersigned Registered Patent Attorney, hereby certify that the documents delivered herewith are being transmitted by telephone facsimile to the United States Patent and Trademark Office on the above date.

The documents being transmitted are as follows:

Cover Letter (1 page) with Certificate of Correction (2 pages) attached

Respectfully submitted,

Per: David J. French

David J. French
Reg. No. 31,229

such documents have been transmitted in accordance with the particulars on the attached telefax confirmation sheet.

Suite 700, 225 Metcalfe Street
Ottawa, Ontario, Canada K2P 1P9
Telephone: 613-567-7824 x 232 x 253
Telefax: 613-567-4689

RECEIVED
CENTRAL FAX CENTER

OCT 21 2005

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: SANDERS, Allan
 Inventor: SANDERS, Allan
 Patent No: 6,883,300 (Serial No 10/617,179)
 Issued: April 26, 2005 (Filed July 11, 2003)
 Title: ASSEMBLY INCLUDING A CHAIN FOR SUSPENDING AN ARTICLE SUCH AS A LIGHT AND FOR CONCEALING AN ELECTRICAL CONDUCTOR
 Art Unit: 3725
 Confirm: 3035
 Our File: RE-SANDE-03.US (5280-03-60)

October 21, 2005
 By Fax 1-571-273-8300

Attention: Certificate of Correction Branch
 Commissioner for Patents
 P.O. Box 1450
 Alexandria, VA 22313-1450
 U.S.A.

Re: CERTIFICATE OF CORRECTION


Dear Sir:

Attached herewith is a Certificate of Correction.

When this patent was issued the amendments which were to be made to para [0024], as requested in our response of 13 December 2004 and not objected to by the Examiner in his Notice of Allowability, were not included. Accordingly please issue the attached Certificate of Correction. As this was a Patent Office error we believe no fee is required.

Respectfully submitted,

per _____


 David J. French
 Reg. No. 31229

Suite 700, 225 Metcalfe Street
 Ottawa, Canada K2P 1P9
 Tel: (613) 567-7824, ext. 253, ext. 232

RECEIVED
CENTRAL FAX CENTER

OCT 21 2005

PTO/SB/44 (04-05)

Approved for use through 04/30/2007. OMB 0651-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTIONPage 1 of 2

PATENT NO. : 6,883,300 B2

APPLICATION NO.: 10/617,179

ISSUE DATE : April 26, 2005

INVENTOR(S) : Allan Sanders

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 59 after "16" insert preferably:

Column 2, line 61 after "link" insert 16:

Column 2, line 61 after "has" insert :

- a) an upper end and a lower end bounding a central opening surrounded by the link 16;
- b) an inside surface facing into said central opening;
- c) two outside sides positioned laterally on either side of said inside surface and directed outwardly from said central opening
- d) a tubular portion within the link 16 serving as a passageway through which a conductor can pass through the length of the link 16.
- e) an inlet aperture 20 and an outlet aperture 22 for the passage of the conductors, said inlet and outlet apertures 20, 22 being located at opposite ends of each link 16, both apertures being located on the inside surface of the link 16, spanning between the side surfaces of each link 16 with at least one of said apertures 20, 22 spanning said split, and
- f) dual tabs 26 extending from the inside surface of each link 16 towards said central opening, positioned adjacent the inlet aperture 20 of said link 16, one on either side of said split to register with the outlet aperture 22 of the next adjacent link 16 and extend respectively along the sides of said adjacent link 16 to which it is mated,

MAILING ADDRESS OF SENDER (Please do not use customer number below):

David J. French/Milton, Geller LLP
Suite 700 225 Metcalfe Street
Ottawa, Canada K2P 1P9

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

JESI AVAILABLE COPY

OCT 26 2005

PTO/SB/44 (04-05)

Approved for use through 04/30/2007. OMB 0651-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTIONPage 2 of 2

PATENT NO. : 6,883,300 B2

APPLICATION NO.: 10/617,179

ISSUE DATE : April 26, 2005

INVENTOR(S) : Allan Sanders

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

the arrangement of the chain being such that with the chain hanging vertically with the links 16 mated to each other, an outlet aperture 22 at the end of one, upper link underlies and registers with an inlet aperture 20 at the end of the next adjacent, lower link 16, so that a conductor can pass through of the outlet aperture 22 of said upper link, through the tubular passageway portion of said one link and then through the inlet aperture 20 of the adjacent link 16 substantially without being exposed to view.

Column 2, line 61 delete [an] and insert The;

Column 2, line 62 delete [on its] formed on the;

Column 2, line 62 after "surface" insert of each link;

Column 2, line 62 delete [suitable] and insert is suitably dimensioned;

Column 2, line 64 after "tubing, and" insert each link 16;

Column 2, line 67 after "the link" insert both apertures spanning between the side surfaces of each link;

Column 3, line 1 after "Fig.3" insert with at least one of said apertures spanning the split;

Column 3, line 8 after "next" insert , mated;

Column 3 line 10 after "assembled" insert by their engagement with opposite sides of the adjacent link.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

David J. French/Milton, Geller LLP
Suite 700 225 Metcalfe Street
Ottawa, Canada K2P 1P9

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-8199 and select option 2.